

BULLDOZER KOMATSU D20P-5 D205-47333

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
BULLDOZER	BULLDOZER	KOMATSU	D20P-5
Serial	Engine	Chassis	Year
D205-47333	4D94-2-23722		
Check Point			
Operator	Cabin		
Monitor Panel	Repair		
Hour Meter Activity	Repair		
Air Condition	Non		
Engine Condition			
Number of Cylinder	4		
Engine Noise	Fair		
Black - White Smoke	Fair		
Type Transmission	Normal		
Gear Working Condition	Manual		
Water Leak from Water Pump	Fair		
Water Leak from Radiator	Fair		
Remark			
Details	More — สภาพภายนอก ต้องซ่อมบำรุง		
Hydraulic System			
Oil leak from Valve-Hose	Normal		
Hyd.Pump Condition	Normal — ใช้งานได้ปกติ		
Hydraulic Oil	Normal		
Hydraulic Cylinder Working Condition			
Lift Blade Cylinder Working Condition	Fair		
Title Blade Cylinder Working Condition	Fair		
Angle Blade Cylinder Working Condition	Normal		
General Working Condition			
Blade Condition	Fair — มีรอยฉีกทะลุ		
The overall condition of the undercarriage	Fair — มีฝุ่น มีสนิม ตามสภาพการใช้งาน		
Type & Size Track Shoe			
Battery Condition	Non		