

AGRICULTURAL TRACTOR KUBOTA L2600 L2600-18471

*** THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	L2600
Serial	Engine	Chassis	Year
L2600-18471	V1500-10140		
Check point			
Operator	Roof		
Monitor Panel	Normal — แสดงผลครบ		
Hour Meter Activity	Normal — 5858		
Air Condition	NONE		
Engine Operation			
Number of Pistons	4 Pistons		
Fuel Type	Diesel		
Engine Noise	Fair		
Black-White Smoke	Fair		
Type Transmition	Manual		
Water Leak form Water Pump	Normal		
Water Leak form Radiater	Normal		
Hydraulic System			
Oil Leak form Velve,Hose	Normal		
HYD. Pump Condition	Repair		
Hydraulic Oil	Repair		
General Working Condition			
Drive Shaft Size	Drive 2		
Special Accessories	NONE		
Gear Working Condition	Normal		
Gear Working Condition PTO	Repair		
Battery	No Have		
Battery Condition	No Good		
Remark			
Details	More — บางรายการไม่สามารถเช็คได้ เนื่องจากเครื่องยนต์ไม่ทำงาน		