AGRICULTURAL TRACTOR KUBOTA M1-75 M74-50395

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	M1-75
Serial	**Engine**	**Chassis**	**Year**
M74-50395	V4302-74884		

Check point	
Operator	Hood
Monitor Panel	Normal – แสดงผลครบ
Hour Meter Activity	Normal – 9703
Air Condition	NONE
Engine Operation	
Number of Pistons	
Fuel Type	Diesel
Engine Noise	Fair
Black-White Smoke	Fair
Type Transmition	Auto
Water Leak form Water Pump	Fair
Water Leak form Radiater	Fair
Hydraulic System	
Oil Leak form Velve,Hose	Repair – รั่วซึม
HYD. Pump Condiction	Fair
Hydraulic Oil	Fair
General Working Condition	
Drive Shaft Size	Drive 4
Special Accessories	NONE – คานยกหน้า ไม่มีใบมีด ไม่มีปุ้งกี๋
Gear Working Condiction	Normal
Gear Working Condition PTO	Repair
Battery	Have
Battery Condition	No Good
Remark	
Details	More – ภายนอกเสื่อมสภาพ ต้องซ่อมบำรุง