

AGRICULTURAL TRACTOR YANMAR YM2700L YM2700L-2853

*** THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	YANMAR	YM2700L
Serial	Engine	Chassis	Year
YM2700L-2853	2TR27-06483		
Check point			
Operator	NONE		
Monitor Panel	NONE		
Hour Meter Activity	Normal — 1001		
Air Condition	NONE		
Engine Operation			
Number of Pistons	2 Pistons		
Fuel Type	Diesel		
Engine Noise	Normal		
Black-White Smoke	Normal		
Type Transmition	Manual		
Water Leak form Water Pump	Fair		
Water Leak form Radiater	Normal		
Hydraulic System			
Oil Leak form Valve,Hose	Fair		
HYD. Pump Conduction	Normal		
Hydraulic Oil	Normal		
General Working Condition			
Drive Shaft Size	Drive 2		
Special Accessories	NONE		
Gear Working Conduction	Normal — เดินหน้าถอยหลังได้		
Gear Working Condition PTO	Normal — ใช้งานได้ปกติ		
Battery	No Have		
Battery Condition	No Good — ต้องพ่วง		
Remark			
Details	More — เบาะไม่มี ต้องซ่อมบำรุง		