AGRICULTURAL TRACTOR KUBOTA KB20 AV-51463

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	KB20
Serial	**Engine**	**Chassis**	**Year**
AV-51463	D1105-605047		

Check point	
Operator	Roof
Monitor Panel	Normal
Hour Meter Activity	Normal – 668
Air Condition	NONE
Engine Operation	
Number of Pistons	3 Pistons
Fuel Type	Diesel
Engine Noise	Repair
Black-White Smoke	Repair – ใช้งานไม่ได้
Type Transmition	Auto
Water Leak form Water Pump	Repair
Water Leak form Radiater	Repair
Hydraulic System	
Oil Leak form Velve,Hose	Fair
HYD. Pump Condiction	Fair
Hydraulic Oil	Fair
General Working Condition	
Drive Shaft Size	Drive 4 – หน้ายาง หลังล้อแทรค
Special Accessories	NONE
Gear Working Condiction	Normal
Gear Working Condition PTO	Repair
Battery	No Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	More – แบตเตอรี่ ไฟเลี้ยง