

SKID LOADER KOMATSU SK714 *37AF00258*

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
LOADER	SKID LOADER	KOMATSU	SK714
Serial	Engine	Chassis	Year
37AF00258	4D88E 18175		2001
Check Point			
Operator	Cabin		
Monitor Panel	Repair		
Hour Meter Activity	Repair		
Air Condition	Repair		
Engine Condition			
Number of Cylinder (Cylinder)	4 Cylinder		
เครื่องยนต์มีเสียงดัง			
Black - White Smoke			
Type Transmission	Normal		
Gear Working Condition			
Water Leak from Water Pump	Repair		
Water Leak from Radiator	Repair		
Hydraulic System			
การรั่วของน้ำมันจากวาล์ว, สายน้ำมัน	Repair		
Hyd.Pump Condition	Repair		
Hydraulic Oil	Repair		
Hydraulic Cylinder Working Condition			
Arm Cylinder Working Condition	Repair		
Bucket Cylinder Working Condition	Repair		
Bucket Cylinder Working Condition	Repair		
สภาพการทำงานทั่วไป / General Working Condition			
Bucket Condition	Repair — ฟุ่ ทุ่		
Battery Condition	Non		
Remark			
Details	More — สถานะจอด ตามสภาพใช้งานไม่ได้		