

MINI EXCAVATOR KOMATSU PC27R-8 11255

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าธรรมเนียมนำเข้า 5%

Category	Type	Maker	Model
EXCAVATOR	MINI EXCAVATOR	KOMATSU	PC27R-8
Serial	Engine	Chassis	Year
11255	3D82AE-3F 10363		1999
Check Point			
Operator	Canopy – เมาะขาด สภาพตามอายุการใช้งาน		
Monitor Panel Condition	Normal		
Hour Meter Activity	Normal – 3260		
Air Condition	Non		
Remark			
Details	More – สภาพภายนอกพอใช้		
Engine Condition			
Number of Cylinder (Cylinder)	3 Cylinder		
Engine Noise	Normal		
Black - White Smoke	Normal		
Water Leak from Water Pump	Normal		
Water Leak from Radiator	Normal		
ระบบน้ำมันไฮดรอลิก/Hydraulic System			
Oil leak from Valve	Normal		
Hyd.Pump Working Condition	Normal – ใช้งานได้ปกติ		
Hydraulic Oil	Normal		
Hydraulic Cylinder Working Condition			
Boom Cylinder Working Condition	Repair – รื้อซ่อม		
Bucket Cylinder Working Condition	Repair – รื้อซ่อม		
Arm Cylinder Working Condition	Repair – รื้อซ่อม		
Blade Cylinder Working Condition	Normal – ขึ้นลงได้ตามปกติ		
General Working Condition			
Swivel Bearing & Swivel Motor Condition	Normal		
The overall condition of the undercarriage	Normal		
Shoe Size (Centimeter)	Centimeter – แทรคยาง30ซม		
Battery Condition	Have		