# FORKLIFT TOYOTA 5FD25 5FD25-73017

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

| Category | Type | Maker | Model |
|---|---|---|---|
| FORKLIFT | FORKLIFT | TOYOTA | 5FD25 |
| **Serial** | **Engine** | **Chassis** | **Year** |
| 5FD25-73017 | 1Z 0085940 | | 1992 |

| Check Point | |
|---|---|
| **Operator** | Canopy – เบาะ ขาด ตามอายุการใช้งาน |
| **Monitor Panel** | Normal – เช็คไม่ได้ |
| **Hour Meter Activity** | Normal – ไม่แสดงผล |
| **Air Condition** | Non |
| **Engine Operation** | |
| **Number of Cylinder** | 4 Cylinder – สตาร์ทไม่ติด ใช้เครื่องยนต์ไม่ได้ |
| **Fuel Type** | Diesel |
| **Engine Noise** | |
| **Black - White Smoke** | |
| **Type Transmission** | Manual |
| **Gear Working Condition** | |
| **Water Leak from Water Pump** | |
| **Water Leak from Radiator** | |
| **Remark** | |
| **Details** | |
| **Hydraulic System** | |
| **Oil leak from Valve,Hose** | |
| **Hyd.Pump Condition** | |
| **Hydraulic Oil** | |
| **Hydraulic Cylinder Working Condition** | |
| **Lift fork Cylinder Working Condition** | |
| **Tilt Mast Cylinder Working Condition** | |
| **General Working Condition** | |
| **SIze of Mast** | 2 Pieces |
| **The Height of Mast** | Centimeter – 300 |
| **Special features of Mast** | Full Free |
| **Special features of Fork** | Hing fork |
| **The Length of Fork** | Centimeter – 90 |
| **Characteristics of Rubber** | Pneumatic Tires – หน้า-หลัง ,หน้าคู่ |
| **Battery Condition** | Have – ต้องพ่วง |