HYD. EXCAVATOR KOBELCO SK200-9 YN13-72455

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
EXCAVATOR	HYD. EXCAVATOR	KOBELCO	SK200-9
Serial	**Engine**	**Chassis**	**Year**
YN13-72455	JO5E TJ26356		2017

Check Point	
Operator	Cabin
Monitor Panel Condition	Normal
Hour Meter Activity	Normal – 7182
Air Condition	Normal
Remark	
Details	
Engine Condition	
Number of Cylinder (Cylinder)	4 Cylinder
Engine Noise	Normal
Black - White Smoke	Normal
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
Hydraulic System	
Oil leak from Valve	Normal
Hyd.Pump Working Condition	Normal
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Repair – รั่วซึม
Bucket Cylinder Working Condition	Normal – สลักหลวมคลอนตามสภาพ
Arm Cylinder Working Condition	Normal – ไม่รั่วไม่ซึม
Blade Cylinder Working Condition	Normal – ไม่มี
General Working Condition	
Swivel Bearing & Swivel Motor Condition	Normal
The overall condition of the undercarriage	Normal – เสื่อมสภาพตามการใช้งาน
Shoe Size (Centimeter)	Centimeter – 70
Battery Condition	Have – สตาร์ทใช้งานได้เลย