

BULLDOZER KOMATSU D20A-6 S206-72717

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
BULLDOZER	BULLDOZER	KOMATSU	D20A-6
Serial	Engine	Chassis	Year
S206-72717	4D95S-W90570		
Check Point			
Operator	Canopy		
Monitor Panel	Normal		
Hour Meter Activity	Normal — 4529		
Air Condition	Non		
Engine Condition			
Number of Cylinder	4		
Engine Noise	Fair		
Black - White Smoke	Fair		
Type Transmission	Normal		
Gear Working Condition	Manual		
Water Leak from Water Pump	Normal		
Water Leak from Radiator	Normal		
Remark			
Details	More — สภาพภายนอก ต้องซ่อมบำรุง		
Hydraulic System			
Oil leak from Valve-Hose	Normal		
Hyd.Pump Condition	Normal — ใช้งานได้ดีปกติ		
Hydraulic Oil	Normal		
Hydraulic Cylinder Working Condition			
Lift Blade Cylinder Working Condition	Normal		
Title Blade Cylinder Working Condition	Normal		
Angle Blade Cylinder Working Condition	Normal		
General Working Condition			
Blade Condition	Normal		
The overall condition of the undercarriage	Normal — มีพู่ มีสปีด ตามสภาพการใช้งาน		
Type & Size Track Shoe			
Battery Condition	Non		