

AGRICULTURAL TRACTOR KUBOTA MD97 M93-50544

\*\*\* THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

| Category             | Type                 | Maker   | Model |
|----------------------|----------------------|---------|-------|
| AGRICULTURAL TRACTOR | AGRICULTURAL TRACTOR | KUBOTA  | MD97  |
| Serial               | Engine               | Chassis | Year  |
| M93-50544            | V4702-WE4611         |         |       |

| Check point                |                                                               |
|----------------------------|---------------------------------------------------------------|
| Operator                   | Hood                                                          |
| Monitor Panel              | Normal – ๖                                                    |
| Hour Meter Activity        |                                                               |
| Air Condition              | NONE                                                          |
| Engine Operation           |                                                               |
| Number of Pistons          |                                                               |
| Fuel Type                  | Diesel                                                        |
| Engine Noise               |                                                               |
| Black-White Smoke          |                                                               |
| Type Transmition           | Auto                                                          |
| Water Leak form Water Pump |                                                               |
| Water Leak form Radiater   |                                                               |
| Hydraulic System           |                                                               |
| Oil Leak form Velve,Hose   |                                                               |
| HYD. Pump Condition        |                                                               |
| Hydraulic Oil              |                                                               |
| General Working Condition  |                                                               |
| Drive Shaft Size           | Drive 4                                                       |
| Special Accessories        | Blade                                                         |
| Gear Working Condition     |                                                               |
| Gear Working Condition PTO |                                                               |
| Battery                    | Have                                                          |
| Battery Condition          | No Good – เสื่อม สภาพ                                         |
| Remark                     |                                                               |
| Details                    | More – บางรายการไม่สามารถเช็คได้ เนื่องจากเครื่องยนต์ไม่ทำงาน |