

AGRICULTURAL TRACTOR KUBOTA M1-75 M74-50395

*** THAILAND DUTY PAID /ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	M1-75
Serial	Engine	Chassis	Year
M74-50395	V4302-74884		
Check point			
Operator	Hood		
Monitor Panel	Normal — แสดงผลครบ		
Hour Meter Activity	Normal — 9703		
Air Condition	NONE		
Engine Operation			
Number of Pistons			
Fuel Type	Diesel		
Engine Noise	Fair		
Black-White Smoke	Fair		
Type Transmition	Auto		
Water Leak form Water Pump	Fair		
Water Leak form Radiater	Fair		
Hydraulic System			
Oil Leak form Velve,Hose	Repair — รั้วซึม		
HYD. Pump Condition	Fair		
Hydraulic Oil	Fair		
General Working Condition			
Drive Shaft Size	Drive 4		
Special Accessories	NONE — คานยกหน้า ไม่มีใบมีด ไม่มีบั้งก็		
Gear Working Condition	Normal		
Gear Working Condition PTO	Repair		
Battery	Have		
Battery Condition	No Good		
Remark			
Details	More — ภายนอกเสื่อมสภาพ ต้องซ่อมบำรุง		