AGRICULTURAL TRACTOR YANMAR YM2700L YM2700L-2853

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	YANMAR	YM2700L
Serial	**Engine**	**Chassis**	**Year**
YM2700L-2853	2TR27-06483		

Check point	
Operator	NONE
Monitor Panel	NONE
Hour Meter Activity	Normal – 1001
Air Condition	NONE
Engine Operation	
Number of Pistons	2 Pistons
Fuel Type	Diesel
Engine Noise	Normal
Black-White Smoke	Normal
Type Transmition	Manual
Water Leak form Water Pump	Fair
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Fair
HYD. Pump Condiction	Normal
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 2
Special Accessories	NONE
Gear Working Condiction	Normal – เดินหน้าถอยหลังได้
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ
Battery	No Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	More – เบาะไม่มี ต้องซ่อมบำรุง