

AGRICULTURAL TRACTOR KUBOTA KB20 AV-51463

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	KB20
Serial	Engine	Chassis	Year
AV-51463	D1105-605047		
Check point			
Operator	Roof		
Monitor Panel	Normal		
Hour Meter Activity	Normal – 668		
Air Condition	NONE		
Engine Operation			
Number of Pistons	3 Pistons		
Fuel Type	Diesel		
Engine Noise	Repair		
Black-White Smoke	Repair – ใช้งานไม่ได้		
Type Transmition	Auto		
Water Leak form Water Pump	Repair		
Water Leak form Radiater	Repair		
Hydraulic System			
Oil Leak form Velve,Hose	Fair		
HYD. Pump Condition	Fair		
Hydraulic Oil	Fair		
General Working Condition			
Drive Shaft Size	Drive 4 – หน้ายาง หลังล้อแทรก		
Special Accessories	NONE		
Gear Working Condition	Normal		
Gear Working Condition PTO	Repair		
Battery	No Have		
Battery Condition	No Good – ต้องพ่วง		
Remark			
Details	More – แบตเตอรี่ ไฟเลี้ยง		