

CRAWLER CRANE MAEDA LC785M-8 32313

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
CRANE	CRAWLER CRANE	MAEDA	LC785M-8
Serial	Engine	Chassis	Year
32313	4D95L-558395		2015
Check Point			
Operator		Cabin — ကနဦးပေးချက်	
Hour Meter Activity		Normal — 2552	
Monitor Panel Condition		Normal	
Air Condition		Normal	
Engine Condition			
Number of Cylinder (Cylinder)		4 Cylinder — 4D95L	
Engine Noise		Normal	
Black - White Smoke		Normal	
Water Leak from Water Pump		Normal	
Water Leak from Radiator		Normal	
Hydraulic System			
Oil leak from Valve		Normal	
Hyd.Pump Working Condition		Normal	
Hydraulic Oil		Normal	
Hydraulic Cylinder Working Condition			
Boom Cylinder Working Condition		Normal	
Arm Cylinder Working Condition		Normal	
General Working Condition			
The overall condition of the undercarriage		Normal	
Shoe Size (Centimeter)		Normal — 50 ဗီ.မီ	
Battery Condition		Good	
Remark			
Details		More	