

AGRICULTURAL TRACTOR KUBOTA KB225-PC BJ-10407

*** THAILAND DUTY PAID / ชำระอากรนำเข้าแล้ว

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	KB225-PC
Serial	Engine	Chassis	Year
BJ-10407	D1305-8E8181		
Check point			
Operator	NONE		
Monitor Panel	Normal		
Hour Meter Activity	Normal — 05038		
Air Condition	NONE		
Engine Operation			
Number of Pistons	3 Pistons		
Fuel Type	Diesel		
Engine Noise	Normal		
Black-White Smoke	Normal		
Type Transmition	Auto		
Water Leak form Water Pump	Normal		
Water Leak form Radiater	Fair		
Hydraulic System			
Oil Leak form Velve,Hose	Fair		
HYD. Pump Condition	Fair		
Hydraulic Oil	Fair		
General Working Condition			
Drive Shaft Size	Drive 4		
Special Accessories	NONE		
Gear Working Condition	Fair		
Gear Working Condition PTO	Repair		
Battery	Have		
Battery Condition	No Good — ไฟเลี้ยง		
Remark			
Details	More — ยางหน้า หลังแทรกคยาง 33 ซม		