

AGRICULTURAL TRACTOR MITSUBISHI D1500V M71B-10561

*** EXCLUDE 20% THAI IMPORT DUTY / มีค่าอากรนำเข้า 20%

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	MITSUBISHI	D1500V
Serial	Engine	Chassis	Year
M71B-10561	15PS 30308		1973
Check point			
Operator	NONE – เกะขาด ตามสภาพ		
Monitor Panel	NONE		
Hour Meter Activity	NONE		
Air Condition	NONE		
Engine Operation			
Number of Pistons	2 Pistons – ไม่เอี่ยม แห้ง		
Fuel Type	Diesel		
Engine Noise	Normal		
Black-White Smoke	Normal		
Type Transmition	Manual		
Water Leak form Water Pump	Normal		
Water Leak form Radiater	Normal		
Hydraulic System			
Oil Leak form Valve,Hose	Normal		
HYD. Pump Condition	Normal – ใช้งานได้		
Hydraulic Oil	Normal		
General Working Condition			
Drive Shaft Size	Drive 2		
Special Accessories	Rotary		
Gear Working Condition	Normal		
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ		
Battery	Have		
Battery Condition	Good – สตาร์ทติด ใช้งานได้เลย		
Remark			
Details			