

AGRICULTURAL TRACTOR KUBOTA B5001 B5001-50584

*** EXCLUDE 20% THAI IMPORT DUTY / มีค่าอากรนำเข้า 20%

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	KUBOTA	B5001
Serial	Engine	Chassis	Year
B5001-50584	Z500-1-271951		1976
Check point			
Operator	NONE – เปรอะขาด ตามสภาพ		
Monitor Panel	NONE		
Hour Meter Activity	NONE		
Air Condition	NONE		
Engine Operation			
Number of Pistons	2 Pistons – ไม่เอี่ยม แห้ง		
Fuel Type	Diesel		
Engine Noise	Normal		
Black-White Smoke	Normal		
Type Transmition	Manual		
Water Leak form Water Pump	Normal		
Water Leak form Radiater	Normal		
Hydraulic System			
Oil Leak form Valve,Hose	Normal		
HYD. Pump Condition	Normal – ใช้งานได้		
Hydraulic Oil	Normal		
General Working Condition			
Drive Shaft Size	Drive 4		
Special Accessories	Rotary – หมุนได้,ขึ้นลงได้		
Gear Working Condition	Normal – เดินหน้าถอยหลังได้		
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ		
Battery	Have		
Battery Condition	No Good – ต้องพ่วง		
Remark			
Details	More – ไม่มีใบมีด		