FORKLIFT KOMATSU FD40W-7 M163-105387

*** EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

Category	Type	Maker	Model
FORKLIFT	FORKLIFT	KOMATSU	FD40W-7
Serial	**Engine**	**Chassis**	**Year**
M163-105387	6D102-26320631		2000

Check Point	
Operator	Canopy
Monitor Panel	Normal — แสดง,ไม่ครบถ้วน
Hour Meter Activity	Normal
Air Condition	Non
Engine Operation	
Number of Cylinder	6 Cylinder
Fuel Type	Diesel
Engine Noise	Fair
Black - White Smoke	Fair
Type Transmission	Manual
Gear Working Condition	Normal
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
Remark	
Details	
Hydraulic System	
Oil leak from Valve,Hose	Normal
Hyd.Pump Condition	Normal
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Lift fork Cylinder Working Condition	Normal
Tilt Mast Cylinder Working Condition	Normal
General Working Condition	
SIze of Mast	2 Pieces
The Height of Mast	Centimeter — 300
Special features of Mast	Normal
Special features of Fork	Normal
The Length of Fork	Centimeter — 120
Characteristics of Rubber	Other — คู่หน้าตัน,คู่หลังลม
Battery Condition	Have — ต้องพ่วง